

TECHNICAL GUIDE

PCB TECHNICAL MASTER GUIDE: DESIGN TO DELIVERY

A comprehensive engineering manual for high-reliability circuit board manufacturing and assembly.


01. PCB Design Basics

Schematic Integrity

Verification of netlists and component footprints is the critical first step. Logical-to-physical synchronization ensures that the fabricated board matches the intended electrical design without error.

Layer Assignment

Strategic stackup configuration optimizes signal integrity and power distribution. Proper plane placement minimizes EMI and provides low-impedance return paths for high-speed signals.



02. Layout Best Practices

Precision Trace Routing

Implementation of controlled impedance routing and differential pair matching. Maintain strict clearance rules to prevent crosstalk and signal degradation across high-density interconnects.

Strategic Decoupling

Placement of bypass capacitors in immediate proximity to power pins. Utilizing wide, short traces to minimize parasitic inductance and ensure stable voltage delivery to active components.


03. Material Selection

Glass Transition (T_g)

Specifying High-T_g materials (170°C+) ensures structural stability during lead-free reflow cycles. This prevents substrate softening and protects the integrity of plated through-holes.

Comparative Tracking Index (CTI)

Selection of laminates with superior CTI values is essential for high-voltage reliability, preventing surface tracking and electrical breakdown in demanding environments.



04. SMT Assembly Process

Advanced Solder Application

Utilizing high-precision stencils and Solder Paste Inspection (SPI) to guarantee exact deposit volume, forming the foundation for robust, defect-free solder joints.

Reflow Profile Optimization

A multi-zone thermal process tailored to the specific thermal mass of the assembly, ensuring uniform wetting and minimizing internal component stress.

05. DFM Design Rules


Trace and Space Precision

Standardized minimum 3/3 mil or 4/4 mil rules ensure high-yield etching. Consistent geometry across the panel is vital for maintaining characteristic impedance.

Annular Ring Integrity

Sufficient annular ring width is maintained to accommodate drill wander and ensure 360° connectivity between the pad and the plated barrel.

PCB DFM DESIGN RULES: OPTIMIZING FOR SUCCESSFUL MANUFACTURING



06. Testing Methods



Flying Probe Diagnostics

High-precision, fixtureless electrical testing for rapid prototyping. Ensures 100% netlist verification without the lead time of custom test fixtures.



In-Circuit Testing (ICT)

Full-scale production testing using custom bed-of-nails fixtures. Provides comprehensive component-level validation and functional verification.

— 07. Inspection

Automated Optical Inspection (AOI)

High-resolution camera systems verify component presence, orientation, and solder fillet quality post-reflow, eliminating human fatigue errors.

Automated X-Ray Inspection (AXI)

Non-destructive internal inspection for BGA and QFN packages. Detects hidden solder voids and bridging that are invisible to optical systems.

X-RAY PENETRATION AND AOI SCAN DATA

— 08. Standards

IPC-A-600 Class 2 & 3

Strict adherence to the acceptability standards for bare printed boards, ensuring internal and external fabrication quality meets global industry benchmarks.

IPC-A-610 Workmanship

Universal criteria for electronic assembly. We maintain Class 3 standards for mission-critical applications where high reliability is paramount.



— 09. Troubleshooting

Cold Joint Remediation

Root cause analysis of insufficient wetting, typically linked to thermal profiling or pad oxidation. Corrective actions ensure long-term mechanical stability.

Etchant Management

Proactive identification of \"acid traps\" during the DFM phase to prevent localized corrosion and trace thinning during the fabrication process.

FAILURE ANALYSIS AND DEFECT RECOGNITION

— 10. Final Quality

Ionic Contamination Analysis

Measuring surface cleanliness to ensure the absence of conductive residues. This prevents dendrite growth and potential field failures in humid environments.

Certified Final Inspection

A rigorous human-verified audit of mechanical dimensions, labeling, and cosmetic finish to ensure the product arrives in perfect corporate condition.